



Service Info



Visual differences

in rocker arm 422 0053 10

Manufacturers: Audi, Seat, Skoda, VW

Models:

Audi: A1, A3
 Seat: Altea, Ibiza, Leon
 Skoda: Fabia, Octavia, Superb
 VW: Eos, Golf IV, Golf Plus, Golf V, Golf VI, Jetta III, Passat (C3_), Polo (6R_), Polo (9N_)

Engines: 1.4 FSI, 1.4 TSI, 1.4 TFSI, 1.6 16V, 1.6 FSI

Part no.: 422 0053 10

OE numbers: 036 109 411 E
 036 109 411 G
 036 109 411 H
 036 109 411 J



Figure 1: Version 1



Figure 2: Version 2

When replacing rocker arm 422 0053 10, either of the versions shown in Figure 1 and Figure 2 may be installed in the vehicle.

Schaeffler Automotive Aftermarket supplies the rocker arm version shown in Figure 1.

Always replace rocker arms in sets!

In the event of a fault in one or more rocker arms, all of the engine rocker arms should be replaced. To avoid multiple repairs and increased costs, always replace the rocker arm and the valve clearance adjustment element at the same time during maintenance.

Note the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
 Fax: +44 (0) 14 32 375 760
 info@luk-as.co.uk
 www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
 AUTOMOTIVE AFTERMARKET

