



Service Info



DMF for vehicles with a double clutch

Note the number of teeth on the starter ring during replacement

Manufacturer: Audi
Seat
ŠKODA
Volkswagen

Transmission: OAM

LuK DMF: 415 0509 09
415 0531 09
415 0545 09
415 0626 09



Image 1: The number of teeth on the starter ring of the new part must match the number of teeth on the old part

For vehicles equipped with dry double clutch transmissions, it is possible to fit different dual mass flywheels (DMFs) on the same models from the listed manufacturers. These DMFs differ in the number of teeth on the starter ring.

When replacing the DMF, the number of teeth on the DMF already installed must therefore be noted. The new part must have exactly the same number of teeth as the old part.

To ensure that the number of teeth matches exactly, the value for the DMF in question is given in the parts catalogue.

A DMF with an incorrect number of teeth will result in malfunctions in the starting system.

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100

