



Service Info



Finger follower 423 0079 10

Visual modification

Manufacturer: Audi, Seat, Skoda

Models:

Audi: A3 (8V1), A3 Sportback (8VA),
A4 (8K2, B8), A4 Avant (8K5, B8),
A4 Allroad (8KH, B8),
A5 (8T3), A5 Sportback (8TA),
A5 Cabriolet (8F7),
A6 (4G2, C7), A6 Avant (4G5, C7),
A7 Sportback (4GA),
A8 (4H_),
Q5 (8R), TT (8J3)

Seat: Leon (5F1), Leon SC (5F5),
Leon ST (5F8)

Skoda: Octavia (5E3), Octavia Combi (5E5)

Engines: 1.8 TFSI, 1.8 TSI, 2.0 TSI, 2.0 TFSI,
2.5 TFSI, 2.8 FSI

Part no.: 423 0079 10

OE number: 06E 109 409 L
06E 109 409 J



Figure 1: 423 0079 10 – Previous design (left) and new design (right)

For the above models, the design of the finger follower has been modified. The finger follower has been given a new part number by the OEM.

As the two designs differ only in terms of their appearance, Schaeffler Automotive Aftermarket will continue to list the new design under the previous part number 423 0079 10.

From a technical point of view, mixed installation of the two designs is possible!

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100

